## Rockwell Commander Type AC11 Elevator Spar Inspection and Report

### Part 1. Aircraft Information

<b>Table 1</b> Aircraft Information				
Model Year				
Model (circle at right)	112 112A 112B 112TC 112TCA 114 114A 114B 114TC 115			
Serial Number				
Total Time Airframe	Current Prop: [ ] 2-Blade [ ] 3-Blade			
Any record of ownership/le	aseback to a	flight school	? [ ] Yes	[ ] No
	For Recording Below <u>Tach <or> Hobbs</or></u>			
Current Time				
Engine Conversion [ ] None [ ] Hot Shot Normalizer [ ] Camarillo Normalizer [ ] 390 Super [ ] 580 Super	Time <u>Installed</u>	Time Installed	Date <u>Installed</u>	
Service Bulletin SB-112- 56B or SB-114-12B in regard to lower fin rib	Time <u>Complied</u>	Time <u>Complied</u>	Date <u>Complied</u>	Number of Rivet Rows <sup>1</sup> [ ] Single Row [ ] Single Row plus Aft Only [ ] Single Row plus 1/2 Row [ ] Two Full Rows
Service Letter SL-112-46 or SL-114-17 in regard to upper rudder spar  [ ] No Record Found	Time <u>Complied</u>	Time <u>Complied</u>	Date <u>Complied</u>	[ ] Cracked Before Repair [ ] Gone Beyond Stop Drills [ ] Never Cracked
Empennage Maintenance, Replacement or Repair Entries (report only most recent) Enter time and date of work from logs and check all boxes below that apply				
Elevators Mentioned			] Left [ ]	Right [ ] Damage History
Replacement of Elevator	'			
Hinge Bushing/Bearing				
Replacement of Fittings				
Trim Tabs Mentioned	[ ] Left [ ] Right [ ] Damage History			
Replacement of	[ ] Either on Left			
Trim Tab Rod Ends	[ ] Either on Right			
Trim Jackscrew Service			] Left [ ]	Right


Technical Advice (nominal fee charged) available. Fee credited toward service kit.

<sup>&</sup>lt;sup>1</sup> SB-112-56B and SB-114-12B prescribed installation of a doubler at the lower fin rib located just beneath the horizontal stabilizer, consisting initially of a "horseshoe" doubler at the aft end, or later a half-rib doubler, or later yet a full-rib doubler. The level of repair is easily discernable by observing the extent of the second (lower) row of rivets forward along the rib skin starting from the aft edge. Note that the upper row of rivets may be obscured underneath the rubber seal.

# Part 2: General Inspection

Note: Do no cleaning until instructed.

[ ] Install the control lock and inspect for detectable play at the locations set forth in Table 2. Any appreciable play heard, felt or seen in the hinges and bearings, and any play in excess of 1/8" total movement at the trailing edges of the elevators and/or trim tabs should be reported by checking the appropriate boxes:



	able 2 ay in Horizontal Tail			
Left Elevator	Right Elevator			
Left Elevator Trailing Edge [ ] More than 1/8" Total Movement [ ] Less than 1/8" Total Movement [ ] Did Not Inspect	Right Elevator Trailing Edge [ ] More than 1/8" Total Movement [ ] Less than 1/8" Total Movement [ ] Did Not Inspect			
Left Elevator Hinges	Right Elevator Hinges			
OutboardMidInboard[ ] Audible[ ] Audible[ ] Audible[ ] Felt[ ] Felt[ ] Felt[ ] Visible[ ] Visible[ ] Visible[ ] No Play[ ] No Play[ ] No Play[ ] DNI²[ ] DNI[ ] DNI	InboardMidOutboard[ ] Audible[ ] Audible[ ] Audible[ ] Felt[ ] Felt[ ] Felt[ ] Visible[ ] Visible[ ] Visible[ ] No Play[ ] No Play[ ] No Play[ ] DNI[ ] DNI[ ] DNI			
Left Trim Tab	Right Trim Tab			
Left Trim Tab Trailing Edge [ ] More than 1/8" Total Movement [ ] Less than 1/8" Total Movement [ ] Did Not Inspect	Right Trim Tab Trailing Edge [ ] More than 1/8" Total Movement [ ] Less than 1/8" Total Movement [ ] Did Not Inspect			
Outboard Inboard Actuator Rod End Rod End Jack Screw  [ ] Felt [ ] Felt [ ] Felt [ ] Visible [ ] Visible [ ] No Play [ ] DNI [ ] DNI [ ] DNI	Actuator Inboard Outboard  Jack Screw Rod End Rod End  [ ] Felt [ ] Felt [ ] Felt  [ ] Visible [ ] Visible [ ] No Play  [ ] DNI [ ] DNI [ ] DNI			
Elevato	or Push Tube			
Play at Elevator Push Tube — Upper Bearing [ ] Audible [ ] Observable (thru the elevator horn port) [ ] No Play [ ] DNI				
	sh Tube – Lower Bearing noving the stinger) [ ] No Play [ ] DNI			

<sup>&</sup>lt;sup>2</sup> Check box if you did not inspect this item.

[ ] Check the torque on the elevator outboard hinge fitting attachment bolts using a 3/8" swivel socket on a ¼" drive extension and torque wrench set to 30 inch pounds, reporting in Table 3 whether the bolts rotate before torque is reached:

Table 3  Torque Check of Attachment of Outboard Elevator Fitting to Elevator				
Left Elevator Outboard Hinge Fitting		Right Elevator Outboard Hinge Fitting		
Upper Outboard [ ] Rotates [ ] No Rotation [ ] DNI <sup>3</sup>	<u>Upper Inboard</u> [ ] Rotates [ ] No Rotation [ ] DNI	<u>Upper Inboard</u> [ ] Rotates [ ] No Rotation [ ] DNI	<u>Upper Outboard</u> [ ] Rotates [ ] No Rotation [ ] DNI	
Lower Outboard [ ] Rotates [ ] No Rotation [ ] DNI	Lower Inboard [ ] Rotates [ ] No Rotation [ ] DNI	Lower Inboard [ ] Rotates [ ] No Rotation [ ] DNI	Lower Outboard  [ ] Rotates [ ] No Rotation [ ] DNI	

#### Part 3: Special Inspection for Spar Cracks

Note: Do no cleaning until instructed.

LJ	Visually inspect the area immediately surrounding the outboard elevator hinge fittings
	attached to the elevator for any cracks or signs of smoke produced by cracks in the
	elevator spar web. If cracks or signs are found, make mental note of areas for re-
	inspection after cleaning.

[ ] Clean the fittings and surrounding spar web and re-inspect for cracks. If cracks are found, the inspection may be ended at this point.

[ ] Check this box if inspection ended at this point, and report results in Table 4.

[ ] Remove the elevator tip and inspect the aft face of the spar web in the area of the fitting by inserting a flexible borescope<sup>4</sup> between the aft end of the outboard elevator rib and the trailing edge of the elevator skin. Generally, it will be possible to insert a scope up to 9 mm diameter. Inspection should cover the areas surrounding the four attachment nuts and extending upward and downward to the elevator skins

and at least 1" inboard and outboard from the nuts.

Typically the spar web inside the elevator is clean, so any "lines" are likely of aluminum smoke generated by motion of cracks.

If viewing is obscured by dirt or grease, it may be possible to spray some cleaner (such as avgas) in through the small tooling hole in the outboard rib, and then re-inspect.

<sup>&</sup>lt;sup>3</sup> Check this box if did not inspect this item.

<sup>&</sup>lt;sup>4</sup> The Bend-a-Light Mini Pro, sold by Aircraft Spruce, and the B5500 Visual Inspection Device, sold by Snap-On, are both reported to work.

If access cannot be gained for inspection using a borescope, or direct viewing is necessary for confirmation of cracks, contact Aerodyme or CPAC for further consultation.

[ ] The inspection is finished at this point. Report the results in Table 4. If cracks have been found, and if possible, take digital pictures for the owner to upload to the survey page.

Table 4 Special Inspection Res	ults		
(at right, check all that apply and record length, or distance, or count as appropriate)	<u>Elev</u> Left	<u>rator</u> Right	Length or Distance or Count
No Defects Found			
Crack Along Upper Edge of Fitting, and How Long?			
Crack Along Lower Edge of Fitting, and How Long?			
Crack Beyond Inboard Edge of Fitting, and How Far?			
Crack Beyond Outboard Edge of Fitting, and How Far?			
Crack Starting/Ending at Bolt Holes, How Many?			
Crack Visible by External Inspection of Elevator			
Crack Visible by Internal Inspection of Elevator			
Crack Visible Only by Dye-Penetrant Inspection			
Other Defect (please describe here)			

## Part 4: Contact Information

Date of Inspection:	
Inspector's Name:	
Best Contact Method:	[ ] Email to
	[ ] Telephone

Please have the results of this report:

- Entered online at <u>www.commander.org/survey</u>
- Scan and email to <a href="mailto:survey@commander.org">survey@commander.org</a>
- Fax to (978) 921-0950

#### Reference Information

Model 112 IPC Figure 2-35 Callout 46 Spar and Detail B Callout 56 Fitting Model 114 IPC Figure 2-35 Callout 46 Spar and Detail A Callout 56 Fitting